

HEALTH AND SAFETY STATEMENT

ISOCYANATES

Our moisture cured urethane coatings contain minimal isocyanates - below acceptable safety standards and less than most 2-part polyurethanes and polyureas

Independent testing has detected only negligible isocyanate traces immediately after our products have been applied because the isocyanates are effectively pre-polymerized in the factory and are held in solution

CARCINOGENS

Though our products contain hazardous materials the occupational risks are at the lower end of the scale because the hazardous materials are premixed

In contrast to 2-part epoxies, polyurethanes and polyureas our products require minimal stirring on-site, are not heated prior to application and are touch-dry within minutes of being applied

Even so, our health and safety recommendation stipulates that all applicators must wear face mask respirators, overalls and gloves to guarantee that people who apply our products do not come into harms way

In over 35 years of use MCU-Coatings® has not been made aware of any issues relating to occupational allergens, reactive diluents or volatile hardeners

