Project Experience





Project information – Cooling Towers

Location: Romania **Project:** Maintenance

Surface Preparation Climatic conditions

Water wash surface concrete 14 °C – 20 °C; RH 80% - 95%

Coatings System

MCU-MASTIC / MCU-FERROGUARD MCU-TOPCOAT

Around 60 older concrete cooling towers needed urgent renovation due to failing concrete.

After concrete repair a thinned layer of MCU-Mastic was applied to penetrate well in the porosity. A finish of MCU-Mastic and MCU-Topcoat was applied on the exterior side and MCU-Ferroguard on the internal side.

MCU-Coatings' paints was the easiest to handle (1 component and no potlife for roller application) and tolerant coating system for these jobs and still offering a very durable and long-term protection. MCU-Mastic and MCU-Ferroguard can be applied direct to concrete.