

## Project Experience Ports and harbours



### Project information

<b>location</b>	Rotterdam The Netherlands	<i>This port facility pilings were severely corroded and had no maintenance for over 15 years. As it was in the main port area within the city limits – abrasive blasting was not allowed. The structure was prepared by hydro jet full removal.</i>
<b>client project</b>	Stolt Neilsen / Vopac Port	
<b>climatic conditions</b>	15 - 21°C 48 - 75% RH	
<b>substrate</b>		
<b>surf. Preparation</b>	WJ 2	
<b>system</b>	MCU-Miozinc MCU-Ferrogard MCU-Ferrogard	